

**Name of Advisory Group:**

Natural Environment Advisory Group

30 June 2022

Discussion Items/Briefing notes	
1	The group believe that a permanent solution to the lighting of beacons and are having preparatory discussions with the local Royal Legion in preparation for the Stewardship Group meeting
2	Disability access to Beacon Hill has been discussed by Beacon Hub and a draft plan will be reviewed w/c 11/7
3	The Village pond path has not progressed and an alternative contractor is being sought
4	A reply has been received from the Seafront Officer. The engineering report indicates that further investigation is required by a specialist. Unfortunately that person is currently ill but will address the issue on return
5	NEAG is consulting with Beacon Hub on how the car park can be opened. It is an item agenda for the Trustees w/c 11/7
6	The damage to the Terraces has not been progressed as we are awaiting a contractor to be appointed by BHCC. Rottingdean Arts have painted the wall and floor surfaces and repaired the storeroom door
7	The path from the Rec to Hoggs Plat has been investigated and action is underway from BHCC and the directors of Hildas Field
8	The ivy growth in the Whiteway has been inspected but the group considers that as a bridle way action cannot be taken. Steyning Rd to Whiteway path has not yet been addressed

Actions	Responsibility
1	Beacon Hill permanent beacon discussions BT On going
2	Plan for disabled access to be provided Beacon HUB/BT On going
3	Pond contractor to be reviewed, planting quote req'd, BT
4	Cliff safety review to be provided BHCC
5	Terrace damage to be repaired BHCC
6	Path from Rec to Hoggs Plat to be cleared BHCC/Hildasfield
7	Review Steyning to Whiteway path obstruction BT O/s
8	Terms of reference to be drafted and proposed to RPC BT/SJ
9	

