



# Health & Safety

## Site Visit Report.



|                        |                         |
|------------------------|-------------------------|
| <b>Report For:</b>     | Larksfield              |
| <b>Conducted By:</b>   | Karen Sweeney GRAD IOSH |
| <b>Date Conducted:</b> | 11/09/2024              |

# Workplace Inspection

## Table of Contents

|    |                                                              |    |
|----|--------------------------------------------------------------|----|
| 1  | Letter                                                       | 4  |
| 2  | Introduction                                                 | 5  |
| 3  | Recommendations Key                                          | 6  |
| 4  | Site Visit Executive Summary                                 | 7  |
| 5  | HS Task Completion Summary                                   | 8  |
| 6  | Displayed Notices and Certificates                           | 9  |
| 7  | Consultation                                                 | 9  |
| 8  | Access and Egress                                            | 9  |
| 9  | Contractors                                                  | 10 |
| 10 | Disabled Discrimination                                      | 10 |
| 11 | Electrical Safety                                            | 10 |
| 12 | Fire - Detection and Alarm                                   | 11 |
| 13 | Fire - Documentation                                         | 12 |
| 14 | Fire - Doors/Emergency Exits                                 | 13 |
| 15 | Fire - Emergency Lighting                                    | 14 |
| 16 | Fire - Extinguishers                                         | 14 |
| 17 | Fire - Monitoring                                            | 15 |
| 18 | Fire - Signage                                               | 16 |
| 19 | First Aid                                                    | 16 |
| 20 | Gas / Oil / Solid Fuel Safety                                | 17 |
| 21 | Health Screening                                             | 17 |
| 22 | Legionella                                                   | 18 |
| 23 | Risk Assessment: General, Young Person and Expectant Mothers | 18 |
| 24 | Training                                                     | 20 |
| 25 | Workplace Health, Safety and Welfare                         | 20 |
| 26 | Asbestos                                                     | 21 |
| 27 | Display Screen Equipment                                     | 21 |
| 28 | Hazardous Substances/COSHH                                   | 21 |
| 29 | Lifting Equipment                                            | 22 |
| 30 | Window Restrictors                                           | 22 |
| 31 | Workspace Inspection Media                                   | 23 |
| 32 | Conclusion                                                   | 38 |

|    |                             |    |
|----|-----------------------------|----|
| 33 | Call Us For Further Support | 39 |
|----|-----------------------------|----|

Harborne Parish Lands Charity

Windmill Lane  
Smethwick  
B66 3EU  
England

17/09/2024

Dear Carolyn,

Please find enclosed the health and safety inspection report that covers matters discussed with either yourself or nominated contacts at your premises on 11/09/2024. The report may identify site-specific hazards or shortcomings in your health and safety management system. If that is the case it will include specific recommendations that will assist in you completing these.


Delay in progressing these recommendations may leave the business open to further scrutiny or possible enforcement action by relevant enforcement authorities.

If there is any area in this report that is unclear or if there are any items you wish to discuss, please contact me via our head office or alternatively on my direct number 07743 975219

It is important to ensure that if you move, alter your business premises or any of your working practices, or you are visited/contacted by an Enforcement Officer, you should inform me or the Health and Safety helpline 03458 444 848 at the earliest possible time so that the appropriate advice can be given.

Finally may I take this opportunity to thank yourself and your staff for the help and co-operation extended to me during my visit.

Yours Sincerely,

A handwritten signature in blue ink, reading 'Karen Sweeney', on a light blue background.

Karen Sweeney GRAD IOSH  
Safety and Health Practitioner

# Introduction

This report is designed to assist you in managing and prioritising the health and safety risks in your workplace.

At Citation, we appreciate that all businesses will have competing demands for their time and resources and that health and safety may not always appear to be the greatest priority. However, it is very important for you to consider the recommended actions contained within this report as they are based upon the observed/stated conditions and your working practices and reflect your legal obligations under health and safety law. The priority rating is provided to assist you in planning the required actions. Whilst you should review each recommended action on its own merits, it is important to remember that all items need to be addressed.

Even the smallest change in employers' or employees' actions or behaviour could reduce (if not eliminate) the potential for an accident occurring, thus avoiding the loss of working time/productivity, and reduce the potential for Enforcement Authority action (at worst leading to a criminal prosecution or intervention costs) or civil claim, that could have a damaging effect on your trading reputation.

This report refers to the condition of the premises at the time of inspection. However, there may be areas that were not inspected and there may have been situations that have arisen since the inspection. We therefore urge you to read the contents of this report in conjunction with the relevant guidance contained within your Health and Safety Policy documentation.

When carrying out inspection visits our consultants will use their experience, skills and expertise to identify matters in respect of which you may not be complying, either totally or in part, with relevant statutory health and safety provisions. However, especially given the finite amount of time that can be allocated to the visits, our consultants may not identify every example of non-compliance and Citation gives no warranty, expressed or implied, that they will do so. Unless you draw the consultant's attention to a specific matter and request his (or our) advice, we cannot be held responsible for any instance of non-compliance that the consultant may not identify.

If you make changes to your business premises/activities/personnel which may affect health and safety, or where there has been an accident, or an Enforcement Officer has contacted you for any reason, and for any other issues or concerns, please contact your consultant or the Citation Health and Safety helpline, 03458 444 848 to ensure that the correct advice can be provided.

You should also regularly monitor and make changes, where necessary, to your health and safety management system, including risk assessments and safe systems of working, training requirements, etc. in order to ensure continued legal compliance. Particular attention should be given following any business changes or workplace related accidents/incidents or near misses.

Citation cannot accept any responsibility for any failure by the company to comply with the recommendations contained within this report, or any changes that are subsequently made in relation to the company's premises, equipment or processes that were not disclosed during the visit.

## Health and Safety Inspection Report

|                             |               |                              |                |
|-----------------------------|---------------|------------------------------|----------------|
| <b>Place of Inspection:</b> | Larksfield    | <b>Date of Inspection:</b>   | 11/09/2024     |
| <b>Name of Consultant:</b>  | Karen Sweeney | <b>For the Attention of:</b> | Carolyn Arnold |

### Priority Definitions:

|                                                                           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
|---------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Immediate<br/>Priority</b><br><br><b>Action must be<br/>taken NOW.</b> | Immediate action is required to remove an observed or stated dangerous condition/practice that is likely to cause an imminent risk of a fatality, serious personal injury or ill health. This also applies to a situation that could lead to a Prohibition Notice being issued by an Enforcing Authority and /or which may lead to legal proceedings being instigated by an Enforcing Authority. An Immediate Action Form will have been provided at the time of the visit. |
| <b>High Priority</b><br><br><b>Act Now.</b>                               | Contravention of statutory requirements that could lead to fatal or serious personal injury, ill health, issuing of an Improvement Notice and / or which may lead to legal proceedings being instigated by the Enforcing Authority. These matters require urgent action.                                                                                                                                                                                                    |
| <b>Medium<br/>Priority</b><br><br><b>Plan Actions.</b>                    | Contravention of statutory requirements which could lead to personal injury or an ill health effect, the receipt of an Enforcement letter and / or legal proceedings being instituted by the Enforcing Authority indicating an area of non-compliance. These matters require a planned programme of action to eliminate or control the risk identified.                                                                                                                     |
| <b>Low Priority</b><br><br><b>Consider<br/>Improvements.</b>              | Recommendations for ensuring compliance with best practice or stated policy and procedures. Enforcement action is less likely, although accident or property damage is possible. The recommendations made are desired improvements, precautions or techniques consistent with good health and safety control and practice.                                                                                                                                                  |

# Executive Summary

---

The Executive Summary and Observations Overview below, highlight matters identified during the visit. The Observations Overview provides a list of the observations only, in order of priority. Full details, including recommended actions can be found in the report below.

## Consultant comments

I would like to thank Max for his time and cooperation during the recent Citation Health & Safety visit and for gathering of and making available the necessary information to prepare this inspection report.

The following report sets out the findings based on a single visit to site. The report shows the areas where improvement is recommended but also the high level of compliance.

The safety management folders, including maintenance records and fire safety records, were well maintained and up to date at the time of the visit. A sample of further positive observations are detailed in the body of the report.

Following on from the visit it is recommended that you prioritise the following actions:

- Although it was good to see that robust window restrictors are in place, these are not subject to regular documented inspections
- Although your legionella risk assessment is reviewed internally, it is recommended that this is now reviewed by a competent person . It was carried out by a competent person in September 2020 and a review of September 2022 was suggested.
- Personal Emergency evacuation plans are recommended for disabled residents

Please be assured that the recommendations made in this report do not outweigh the many positive health and safety observations made at the time of my inspection. It was clear to see that management and staff are dedicated to managing health and safety effectively in line with current legislation and best practise. Their ability to do this is emphasised by the compliance identified within this report.

Areas highlighted in this document can be easily rectified and I am confident that quick action will be taken. However, if you require further assistance please do not hesitate to contact either myself or the Advice Line.

We can also provide face to face support through additional consultancy, including risk assessment support. If you're interested to find out more, please call **0345 241 5250** or email [additional services@citation.co.uk](mailto:additional services@citation.co.uk) and one of our team will be more than happy to help.

Thank you again for assisting me during the visit.

Karen Sweeney

|                                   |      |
|-----------------------------------|------|
| <b>Non Compliance - Immediate</b> | 0.   |
| <b>Non Compliance - High</b>      | 1.   |
| <b>Non Compliance - Medium</b>    | 2.   |
| <b>Non Compliance - Low</b>       | 0.   |
| <b>Compliance</b>                 | 122. |

### **Progress since your last inspection**

There were 2 observations raised in your previous visit dated 20/09/2023.

2 of these have been marked as completed. Any outstanding tasks are included as observations in this report.

## Observations Overview

### **High**

#### **Fire - Documentation**

There was no procedure in place for evacuating disabled persons from the premises in the event of an emergency.

---

### **Medium**

#### **Legionella**

Although reviewed internally, the legionella risk assessment completed by a competent person was completed in September 2020 and had a suggested review date of September 2022

#### **Window Restrictors**

Although robust window restrictors are in place on first floor windows and these are checked, these checks are not documented

---

## Displayed Notices and Certificates


### Positive observations

An up to date employers liability compulsory insurance certificate was seen on display. This is valid until 24/09/2024

There is an up to date health and safety policy on display. This has been signed by the CEO

There is an up to date health and safety law poster

No smoking signs are displayed in prominent locations to indicate that the premises is classed as 'smoke-free' - This includes vaping.



[Employers liability insurance valid until 24-09-2024](#)



[HS Law poster](#)



[HS Policy statement valid until 23-11-2024](#)



[No smoking or vaping](#)

## Consultation

### Positive observations

There are regular Building Managers Meetings and one to one meetings are held once every 2 weeks, where health and safety matters can be raised/ discussed

## **Access and Egress**

### **Positive observations**

There is safe access and egress throughout

## **Contractors**

### **Positive observations**

Contractors are dealt with centrally by Head Office. Checks are carried out of a contractors insurance and risk assessments and method statements requested

## **Disabled Discrimination**

### **Positive observations**

Disabled alarms / Life line is provided. Documented checks are carried out.

## **Electrical Safety**

### **Positive observations**

An up to date Electrical installation Condition Report was seen. The report is dated 27/09/2020

The Electrical Installation / fixed wiring was certified as satisfactory

Portable electrical appliances have undergone electrical safety testing. This was last undertaken on 31/07/2024. Appliances are labelled.



[Electrical  
Safety Test  
31-07-2024](#)

## Fire - Detection and Alarm

### Positive observations

Fire alarm activation / call points were seen throughout the premises and are securely fastened to the structure of the building.

The fire alarm is on a service and maintenance contract and tested on a regular basis. The fire alarm system was last serviced on 22/07/2024

Weekly tests of the fire alarm system are carried out and recorded in the fire log book. Last undertaken 06/09/2024

The fire alarm panel was free from faults at the time of inspection.


Appropriate 'flame and finger' signs were seen in an easy to view position, close to the call/activation points to ensure that they can be spotted quickly in an emergency.



[Fire Alarm  
panel no faults](#)



[Fire Alarm call  
point clearly  
indicated](#)



[Fire Alarm  
weekly test  
06-09-2024](#)

# Observations and recommendations

## Fire - Documentation

### Observation

There was no procedure in place for evacuating disabled persons from the premises in the event of an emergency.

### Recommendation

Implement a procedure for evacuating disabled members of staff and visitors in the event of an emergency.

Ensure all members of staff are familiar with this procedure.

Priority : High

Responsible Person : Carolyn Arnold

Recommended Deadline Date : 15/10/2024

---

### Positive observations

There is a suitable and sufficient fire risk assessment in place and is subject to regular review. The fire risk assessment is dated 29/04/2023 and was last reviewed 30/04/2024. When complete actions are signed off.




[Fire Risk  
Assessment -  
dated 29-04-  
2024 -  
reviewed 30-  
04-2024](#)

There is a fire floor plan which shows the fire zones on display next to the fire alarm panel.



### [Fire Floor plan](#)

Documented fire procedures are on display



### [Fire Evacuation procedures on display](#)

The Building Manager has undertaken Fire Marshal training on Atlas.

## **Fire - Doors/Emergency Exits**

### **Positive observations**

Suitable fire doors have been installed

Fire doors had suitable signage indicating they were to be kept closed

Fire doors have self closers

It was good to see that Fire doors are not wedged or propped open

Fire doors appeared to close correctly against their frames



[Fire door appropriate signage](#)




[Fire Door self closers seen](#)

## Fire - Emergency Lighting

### Positive observations

Emergency lighting is installed. This is serviced by a competent person. Last service took place 18/01/2024

Monthly checks of the emergency lighting are carried out and recorded in the fire log book. Last undertaken 03/09/2024



[Emergency Lighting monthly check 03-09-2024](#)

## Fire - Extinguishers

### Positive observations

Fire extinguishers are available throughout the premises and on a service and maintenance contract.


The fire extinguishers are within their annual service date (in line with BS5306:Part 3). The last service was carried out 18/01/2024

Fire extinguishers are subject to monthly inspections. Last undertaken 03/09/2024

Fire extinguishers were positioned in their allocated place. They are clearly identified with the correct fire safety signage displayed next to them so a user knows exactly what the extinguisher can be used for.

The fire extinguishers located around the premises appeared in good working order. The security tags were seen to be intact.

Fire extinguisher training is carried out on Atlas.



[Fire Extinguisher Monthly check 03-09-2024](#)



[Fire Extinguishers on suitable stand](#)




[Fire extinguisher service 18-01-2024](#)

## Fire - Monitoring


### Positive observations

Fire evacuation drills are carried out on a regular basis at least once every 6 months and are recorded in the fire log book. The last drill was carried out on 02/08/2024


A fire log book is used to record fire safety checks. In addition to being used to record the fire evacuation drill, monthly checks to the fire extinguishers and emergency lighting, weekly fire alarm tests, fire door checks and checks of the fire escape routes are checked.



[Fire door  
weekly check  
10-09-2024](#)



[Fire escape  
route weekly  
test 10-09-  
2024](#)



[Fire Drill 02-  
08-2024](#)

## Fire - Signage

### Positive observations

Fire escape routes are clearly marked and indicate the nearest escape route

The fire assembly point is indicated on fire action notices. It is located in the carpark and has clear signage. The assembly point was seen to be unobstructed.



[Fire Action  
Notice](#)



[Fire escape  
route  
indicated](#)



[Fire Assembly  
point](#)

## First Aid


### Positive observations

A well stocked first aid kit was seen. Items appeared to be in good order.



[Well stocked  
first aid kit  
and first aid  
notice](#)

The building manager has undertaken first aid training. Valid certification seen. This expires in November 2024.



[First Aid  
certificate  
valid until 14-  
11-2024](#)

## **Gas / Oil / Solid Fuel Safety**

### **Positive observations**

Gas appliances are inspected annually by a registered Gas Safe engineer and there is relevant documentation available. Last undertaken 15/07/2024

## **Health Screening**

### **Positive observations**

A health screening questionnaire is completed on induction

# Legionella

## Observation

Although reviewed internally, the legionella risk assessment completed by a competent person was completed in September 2020 and had a suggested review date of September 2022

## Recommendation

It is important to ensure that the Legionella risk assessment is reviewed on a regular basis or if there is a reason to believe that the original assessment may no longer be valid.

It is recommended that a review is carried out by a competent person.

Priority : Medium

Responsible Person : Carolyn Arnold

Recommended Deadline Date : 29/10/2024


---

## Positive observations

A legionella risk assessment has been undertaken by a competent person. This was last done 09/09/2020 and is reviewed annually internally.

Monitoring is carried out, including flushing and is recorded in the log book

Shower disinfection and cleaning is carried out



[Legionella risk assessment Larksfield 09-09-2020](#)

# **Risk Assessment: General, Young Person and Expectant Mothers**

## **Positive observations**

Risk assessments have been completed for each individual scheme on Atlas. These are reviewed annually and are shared with employees on Atlas

The risk assessments cover:

- Adverse weather
- Animal bites / Animal scratches
- Back injury
- Bin store / Broken glass
- carpet cleaning machine
- Carrying cash
- Challenging behaviour / Violence at work
- Cleaning activity chemical use / Skin burns/ Skin irritants / Respiratory
- contractors working close by
- COVID-19
- Decorations
- Display screen equipment use / Work Equipment (office)
- Driving at work
- Dust
- Electricity
- Fire
- Gaining personal benefit by abusing residents
- Hand tools / Sharp cutting tools / Trapping Fingers / Work Equipment (Power tools) / Wood Working machinery.
- home visits
- hot liquids/ surfaces
- Legionella
- Lone working / Call out 24 hours

## **Training**

### **Positive observations**

Health and Safety training is carried out on the Atlas platform. Training modules carried out include:

- Health and Safety Awareness
- Fire Safety awareness
- Fire Extinguisher Use
- Fire Marshal
- COSHH Awareness
- PPE Use
- Manual Handling
- Ladders and Step ladders
- Legionella and Legionnaires Disease awareness
- Asbestos awareness
- DSE
- Infection Control

Health and safety training is provided on induction. The induction process is documented.

## **Workplace Health, Safety and Welfare**

### **Positive observations**

Housekeeping is maintained to a very high standard across the site.

Toilet facilities were seen to be maintained in a clean, hygienic and orderly condition.

## **Asbestos**

### **Positive observations**

An asbestos survey was seen dated 17/12/2023. It was confirmed that there is no asbestos

## **Display Screen Equipment**

### **Positive observations**

DSE assessments are completed.

Staff have undertaken training in DSE use.

## **Hazardous Substances/COSHH**

### **Positive observations**

COSHH assessments have been carried out for cleaning products used. This includes:


- All purpose cleaner
- Cream Cleaner
- Disinfectant
- Jeyes Fluid
- Multi-surface Cleaner
- Toilet cleaner
- Washing up liquid

These are reviewed annually. Last review 23/05/2024

## **Lifting Equipment**

### **Positive observations**

The passenger lift is subject to thorough examination as is required by the Lifting Operations and Lifting Equipment Regulations 1998 (LOLER). This was last undertaken 19/03/2024



[LOLER 19-03-2024](#)

## **Window Restrictors**

## Observation

Although robust window restrictors are in place on first floor windows and these are checked, these checks are not documented

## Recommendation

Daily inspections should be undertaken of all opening windows / window restrictors to ensure that have not become damaged. Details of this inspection should be recorded on file for inspection by any interested party.

Priority : Medium

Responsible Person : Carolyn Arnold

Recommended Deadline Date : 29/10/2024



[Window restrictors are robust - Documented inspection regime recommended](#)

---

# Workplace Inspection Media


## Window Restrictors



[Window restrictors are robust - Documented inspection regime recommended](#)


## Positive Observations Media

## Displayed Notices and Certificates




Employers liability insurance valid until  
24-09-2024

## Displayed Notices and Certificates



HS Law poster

## Displayed Notices and Certificates




[HS Policy statement valid until 23-11-2024](#)

## Displayed Notices and Certificates



[No smoking or vaping](#)

## Electrical Safety



[Electrical Safety Test 31-07-2024](#)

## Fire - Detection and Alarm



[Fire Alarm panel no faults](#)

## Fire - Detection and Alarm



[Fire Alarm call point clearly indicated](#)

## Fire - Detection and Alarm

Fire Alarm Weekly Tests

| Date    | Time  | Call Point |          | Result Details of Faults | Person Carrying Out Test | Fault Cleared |    | Signature |
|---------|-------|------------|----------|--------------------------|--------------------------|---------------|----|-----------|
|         |       | Zone       | Location |                          |                          | Yes           | No |           |
| 21.6.24 | 12.15 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 28.6.24 | 16.30 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 5.7.24  | 12.40 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 12.7.24 | 13.10 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 19.7.24 | 12.10 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 26.7.24 | 12.00 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 2.8.24  | 12.15 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 9.8.24  | 13.10 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 16.8.24 | 14.20 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 23.8.24 | 12.30 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 30.8.24 | 13.30 | 1          | LF       | none                     | M. BONE                  |               |    |           |
| 6.9.24  | 10.50 | 1          | LF       | none                     | M. BONE                  |               |    |           |


[Fire Alarm weekly test 06-09-2024](#)

## Fire - Documentation




[Fire Risk Assessment - dated 29-04-2024 - reviewed 30-04-2024](#)

## Fire - Documentation



[Fire Floor plan](#)

## Fire - Documentation




[Fire Evacuation procedures on display](#)

## Fire - Doors/Emergency Exits



[Fire door appropriate signage](#)

Fire - Doors/Emergency Exits




Fire - Emergency Lighting

[illegible]

## Fire - Extinguishers

[illegible]

## Fire - Extinguishers



## Fire - Extinguishers



[Fire extinguisher service 18-01-2024](#)

## Fire - Monitoring

| Date    | Location of Door | Door No. | Satisfactory |  | Defect/Action Taken | Signature |
|---------|------------------|----------|--------------|--|---------------------|-----------|
|         |                  |          | Yes / No     |  |                     |           |
| 12.7.24 | Common Area East | 1-14     | YES          |  | None                | ✓         |
| 23.7.24 | Common Area East | 2        | YES          |  | None                | ✓         |
| 9.8.24  | 11               | 11       | YES          |  | None                | ✓         |
| 15.8.24 | 11               | 11       | YES          |  | None                | ✓         |
| 20.8.24 | 11               | 11       | YES          |  | None                | ✓         |
| 23.8.24 | 11               | 11       | YES          |  | None                | ✓         |
| 3.9.24  | 11               | 11       | YES          |  | None                | ✓         |
| 10.9.24 | 11               | 11       | YES          |  | None                | ✓         |

[Fire door weekly check 10-09-2024](#)

## Fire - Monitoring

| Date    | Location of Escape Route | Satisfactory |  | Defect / Action Taken | Signature |
|---------|--------------------------|--------------|--|-----------------------|-----------|
|         |                          | Yes / No     |  |                       |           |
| 12.7.24 | Area 1                   | YES          |  | None                  | ✓         |
| 23.7.24 | Area 1                   | YES          |  | None                  | ✓         |
| 9.8.24  | 11                       | YES          |  | None                  | ✓         |
| 15.8.24 | 11                       | YES          |  | None                  | ✓         |
| 20.8.24 | 11                       | YES          |  | None                  | ✓         |
| 23.8.24 | 11                       | YES          |  | None                  | ✓         |
| 3.9.24  | 11                       | YES          |  | None                  | ✓         |
| 10.9.24 | 11                       | YES          |  | None                  | ✓         |

[Fire escape route weekly test 10-09-2024](#)

## Fire - Monitoring

| Date of Drill | Name of Drill Co-ordinator | Time of Drill | Evacuation Time Taken | Remarks | Signature |
|---------------|----------------------------|---------------|-----------------------|---------|-----------|
| 6.2.23        | Chadwick                   | 10.15         | ---                   | ---     | CA        |
| 5.6.23        | Chadwick                   | 12.55         | ---                   | ---     | CA        |
| 7.2.24        | Chadwick                   | 13.55         | ---                   | ---     | CA        |
| 2.5.24        | Chadwick                   | 14.15         | ---                   | ---     | CA        |

[Fire Drill 02-08-2024](#)

## Fire - Signage



[Fire Action Notice](#)

## Fire - Signage



[Fire escape route indicated](#)

## Fire - Signage




[Fire Assembly point](#)

## First Aid




[Well stocked first aid kit and first aid notice](#)

## First Aid



[First Aid certificate valid until 14-11-2024](#)

## Legionella



[Legionella risk assessment Larksfield 09-09-2020](#)

Lifting Equipment

lenovo

Umschues/HEALTH%20&%20SAFETY/2024%20Health%20&%20Safety/Larksfeld/LF/Zurich/LF%2019.03.24.pdf

Address at which the examination was made: LARKSFELD WINOMILL LANE SMETHWICK B66 3ET

| Item Status                                                                               | No defects (OK)                                               |
|-------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| 1. Client No / Serial No                                                                  | 1 / 10879                                                     |
| 2. Description of equipment                                                               | Electric Hydraulic Passenger/Goods Lift Dated Acting 2 Floors |
| 3. Location                                                                               | Resident Halls                                                |
| 4. Name of manufacturer                                                                   | Perman Lifts                                                  |
| 5. Year of manufacture                                                                    | 1994                                                          |
| 6. Safe working load                                                                      | 2 Persons or 630 kg                                           |
| 7. Type of examination / Frequency / Written scheme                                       | PERIODIC / 6 monthly / No Scheme (DL2-KPM)                    |
| 8. Remarks                                                                                |                                                               |
| (a) Defects which require corrective action before further use or before a specified date | None                                                          |
| (b) Defects requiring corrective action as soon as reasonably practicable                 | None                                                          |
| (c) Observations                                                                          |                                                               |
| (d) Date of previous thorough examination                                                 | 27/06/2023                                                    |
| (e) Latest date by which the next thorough examination should be carried out              | 18/09/2024                                                    |

I declare that the above equipment has been thoroughly examined on 19/03/2024 and, provided that the recorded any defects stated above, this equipment is safe to operate. The responsibility to ensure the proper use of the equipment is placed on the user. I am authorised to issue this certificate in accordance with the provisions of the Lifting Operations and Lifting Equipment Regulations 1998 (LOLER) and the Lifting Equipment Regulations 2007 (LER).

Authorised by: Stephen Mills  
Designation: Engineer

Authorised by: Stephen Mills  
Designation: Engineer

Authorised by: Stephen Mills  
Designation: Engineer

[LOLER 19-03-2024](#)



## **Conclusion**

The assessor believes that the information contained within this inspection report to be correct at the time of printing. The report is based on matters that were observed or came to the attention of the assessor at the time of the visit and should not be relied on as an exhaustive record of all possible risks or hazards that may exist. Hazards associated with the organisation's business should be addressed during the risk assessment process.

During the course of the inspection, not all areas within the premises or equipment may have been inspected, however, any issues that were apparent and visible at the time were either verbally commented upon or included in this report.


It will be important to ensure that if any new equipment is introduced into the organisation or any new work activities commence, appropriate risk assessments are compiled to comply with the Provision and Use of Work Equipment Regulations and any training that is required is completed by relevant members of staff.

In order to maintain the integrity of the inspection process and to protect all parties, the assessors will not divulge the contents of the inspection report to any unauthorised person without prior agreement or if legally obligated to do so.

### **Sign Off:**

Client Representative: Carolyn Arnold

Consultant:

A handwritten signature in blue ink, appearing to read 'Karen Sum', is written over a light blue rectangular background.

**Kings Court, Water Lane, Wilmslow, Cheshire, SK9 5AR**

**[www.citation.co.uk](http://www.citation.co.uk)**



# How Citation can help

For any further information please get in  
touch with us on **0345 844 1111**

